



NOTES

1. No lap joints over welds.
2. Coat ceiling and shell first.
3. When only coating bottom and up 18 inches, coat shell and bottom simultaneously.
4. Light brush blast of edge required only when maximum drying time between coatings has been exceeded.



SHELL OR TANK CEILING



SHELL TO BOTTOM